



Equipment Required for Testing/Work

NOTE: Please be dressed for work for your interview, noting required gear below. Applicants should be clean-shaven for the use of respirators during testing.

SHIP FITTER

1. Safety-toed Boots
2. Long Sleeve Shirt
3. Hard Hat
4. Safety Glasses
5. Leather Welding Gloves
6. Ear Protection
7. Striker
8. Face Shield
9. Tape Measure
10. Combination Square
11. Needle Nose Pliers
12. Chipping Hammer
13. Rain Gear (if necessary)

WELDER

1. Safety-toed Boots
2. Long Sleeve Shirt
3. Hard Hat
4. Safety Glasses
5. Leather Welding Gloves
6. Ear Protection
7. Welding Hood and Lenses
8. Chipping Hammer
9. Leather Welding Sleeves (cover shoulder)
10. Wire Brush
11. Needle Nose Pliers
12. Rain Gear (if necessary)

PIPE FITTER

1. Safety-toed Boots
2. Long Sleeve Shirt
3. Hard Hat
4. Safety Glasses
5. Leather Welding Gloves
6. Striker
7. Face Shield
8. Combination Square
9. Chipping Hammer
10. Torpedo Level
11. Wrap Around
12. Needle Nose Pliers
13. 2 Ft Square
14. 2 Ft Level
15. Chalk Line
16. Wrap Around (Only for certain facilities)
17. Wrenches (adjustable; pipe)
18. Tape Measure
19. Rain Gear (if necessary)

TACKER

1. Safety-toed Boots
2. Long Sleeve Shirt
3. Hard Hat
4. Safety Glasses
5. Leather Welding Gloves
6. Welding Shield
7. Chipping Hammer
8. Leather Welding Sleeves (cover shoulder)
9. Wire Brush
10. Welding Whip (Only for certain facilities)
11. Rain Gear (if necessary)